

Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control

✓

Project Name: Hickory View	Date: 7/30/12
Location: <del>Hickory</del> Hickory Grove Rd Big Flats	Permit #: NYR10V597
Weather Conditions: mostly cloudy	Entry Time: 1:45p
On Site Representative Present: no one on site inc	Exit Time: 2:13
Sketch of Project site Include Disturbed Areas: last insp. 7/2/12 Satisfactory	

Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
X			All erosion and sediment control measures maintained properly
	X		Are there currently more than 5 acres disturbed w/o prior approval
X			Have stabilization measures been initiated in inactive areas
X			Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?

Comments:

- Monitor the two infiltration areas to the Northeast of property - erosion has started.

- Stockpile next to Hickory Grove is falling into the infiltration basin

Satisfactory
  Marginal
  Unsatisfactory

Date: 7/30/12 Inspector: Jessica Verrigin

\* No rain since 7/27 and basins are still holding water



851 Chemung Street  
 Horseheads, New York 14845  
 Ph. 607.796.2216

<b>PROJECT:</b>	Hickory View Apartments
	Big Flats (T)
	Municipal Inspection
	July 30, 2012
<b>BY</b>	Jessica Verrigni, CPESC, CPSWQ



Contractor staging yard and stockpile area- the stockpile has been hydroseeded.



Infiltration trench BCD is still holding water.



Erosion started on the side slope of infiltration BCD.



Infiltration trench A- major erosion has started on the side slope.



851 Chemung Street  
Horseheads, New York 14845  
Ph. 607.796.2216

**PROJECT:** Hickory View Apartments  
Big Flats (T)  
Municipal Inspection  
July 30, 2012

**BY** Jessica Verrigni, CPESC, CPSWQ



Infiltration trench F1.



Infiltration trench F2. Soil stockpile is too close to the edge of the basin (spoke with Dave of Wenzel).



Infiltration F3- holding lots of water.



Overall site condition.



851 Chemung Street  
Horseheads, New York 14845  
Ph. 607.796.2216

**PROJECT:** Hickory View Apartments  
Big Flats (T)  
Municipal Inspection  
July 30, 2012

**BY** Jessica Verrigni, CPESC, CPSWQ



Overall site condition.



Stormwater pond 1A.



Sanitary tie in.



West side of construction area where active filling is occurring.