

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control

Project Name	Hickory View Apartments	Date	12/14/12
Location	Hickory Grove Rd	Permit #	
Weather Conditions	sunny - cool	Entry Time:	2:09
On-Site Representative Present:	Elmira Structures	Exit Time:	2:38

Sketch of Project site-Include Disturbed Areas:

Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
	X		All erosion and sediment control measures maintained properly
	X		Are there currently more than 5 acres disturbed w/o prior approval
X	X		Have stabilization measures been initiated in inactive areas
X			Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?

Need to print current inspections and keep on site

Comments:

Silt Fence repair needed next to Building 3, 2 corners of the pond, and next to Hickory Grove road between F2 + F3.

Concrete Washout - Even though concrete is almost wrapped up - clean up concrete piles and remove old (full) washout areas.

Satisfactory Marginal Unsatisfactory

Date	12/14/12	Inspector	Jessica Kerrigan
------	----------	-----------	------------------

Stabilization - (A) Area where structures were piled (Bldg 13) needs to be re-graded and stabilized

(B) Areas where infiltration K is needs stabilization

(C) Areas mulch seeded by Bldg 5, 7, 8 + 9 most likely needs mulch.



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Hickory View
Town of Big Flats
Municipal Inspection
December 14, 2012

BY Jessica Verrigni, CPESC, CPSWQ



Silt fence needing repair.



Concrete washout was full so someone washed out next to it.



Infiltration K will need stabilization.



Stockpiles that are actively being built.



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Hickory View
Town of Big Flats
Municipal Inspection
December 14, 2012

BY Jessica Verrigni, CPESC, CPSWQ



Concrete wash out in contractor yard was moved. A truck washed out next to the area that the washout was located.



Infiltration trench BCD- Flat area was stabilized in November. But then it was utilized for building panel storage. Needs stabilization now that panels are up.

