

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control

Project Name Biltmore Crossing Apartments	Date 5-1-15
Location Biltmore Drive Town of Horseheads	Permit # NYR10X559
Weather Conditions <i>Sunny</i>	Entry Time: <i>8:39</i>
On-Site Representative Present: no construction personnel on site	Exit Time: <i>9:15</i>

Construction Site Notes:

-top soiling of bare soil is occuring. All other activities has ceased.

Yes	No	N/A	
	<input checked="" type="checkbox"/>		All erosion and sediment control measures installed/constructed
		<input checked="" type="checkbox"/>	All erosion and sediment control measures maintained properly
	<input checked="" type="checkbox"/>		Are there currently more than 5 acres disturbed w/o prior approval
	<input checked="" type="checkbox"/>		Have stabilization measures been initiated in inactive areas
<input checked="" type="checkbox"/>			Are permanent stormwater control measures being implemented
	<input checked="" type="checkbox"/>		Was there a discharge into the receiving water on the day of inspection
	<input checked="" type="checkbox"/>		Evidence of turbidity or oil in the receiving waters
<input checked="" type="checkbox"/>			Are weekly inspections being performed?
<input checked="" type="checkbox"/>			Are the inspections being performed by a qualified individual?

Corrections Needed: -silt sock was removed prior to stabilization- not permitted until final stabilization occurs.

-swale in front of building G is not installed.

-Rain garden 2 not installed. Reason garden 1 not complete. Our office will want to see soil media and some used during construction of these.

-soil around building d and c is compacted and not growing grass. This requires repairs.

-1' diversion berm between bldg. D and pond is not installed.

-swale between building c and community building not constricted.

Satisfactory	Marginal <input checked="" type="checkbox"/>	Unsatisfactory
Date <i>5/1/15</i>	Inspector <i>Josanna Verrigni</i>	



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT:	Biltmore Apartments
	Town of Horseheads
	Municipal Inspection
	May 1, 2015
BY	Jessica Verrigni, CPESC, CPSWQ



Swale in front of Building E is eroded and not stabilized.

Rain Garden 1 is partially installed but sediment is getting into it. We will want to see the soil media prior to its installation.



Areas around the Community Building and building C are not growing grass. These areas do not look like they will be suitable for growth-re-grading is necessary.

Pond will need to have sediment cleaned out of it prior to close out. Permanent stabilization is required. 1 foot berm pond and Building D has not been constructed.



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT:	Biltmore Apartments
	Town of Horseheads
	Municipal Inspection
	April 30, 2015
BY	Jessica Verrigni, CPESC, CPSWQ



Erosion is occurring in the swale next to Biltmore drive and Building G. Light posts may be causing. Swale needs re-grading and stabilization.

Many steep slopes around the buildings have yet to be topsoiled and stabilized.



Rain Garden #2 has not been installed.

Swale in front of Building G has not been constructed.