

Website Updated:
 Active Construction List
 Updated:

Chemung County Stormwater
 Construction Inspection
 Erosion and Sediment Control



Project Name JACKSON FARM STORMWATER POND	Date 10-1-2015
Location Chambers Road Big Flats	Permit #NYR10Z268
Weather Conditions <i>Overcast - cold</i>	Entry Time: <i>11:52</i>
On-Site Representative Present: none	Exit Time: <i>12:20</i>

Construction Site Notes:

-no construction occurring at this time

Yes	No	N/A	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	All erosion and sediment control measures installed/constructed
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	All erosion and sediment control measures maintained properly
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Are there currently more than 5 acres disturbed w/o prior approval
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Have stabilization measures been initiated in inactive areas
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Are permanent stormwater control measures being implemented
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Was there a discharge into the receiving water on the day of inspection
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Evidence of turbidity or oil in the receiving waters
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Are weekly inspections being performed?
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Are the inspections being performed by a qualified individual?

Corrections Needed:

- no issues at this time.

Satisfactory *X* Marginal Unsatisfactory



Date *10/1/15* Inspector *Jessica Carrigini*



CHEMUNG
COUNTY
STORMWATER
COALITION

851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT:	Jackson Farm
	Town of Big Flats
	Inspection
	October 1, 2015
BY	Jessica Verrigni, CPESC, CPSWQ



No discharge to creek. Creek running clear.

