

**Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control**



Project Name Barrington West Lot 85			Date 3-18-2020
Location Wexton Court, Horeseheads (T), NY			Permit # NYR11F212
Weather Conditions sunny, mild			Entry Time: 1:43 pm
On-Site Representative Present: none			Exit Time: 1:55 pm
Construction Site Notes:			
-Home is complete. All areas stabilized with mulch until final grading can be completed.			
Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
X			All erosion and sediment control measures maintained properly
	X		Are there currently more than 5 acres disturbed w/o prior approval
X			Have stabilization measures been initiated in inactive areas
		X	Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?
Corrections Needed:			
NONE			
Satisfactory XX Marginal Unsatisfactory			
Date 3-18-2020		Inspector <i>Jessica Verrigni</i>	



COUNTY OF CHEMUNG
Chemung County Stormwater Coalition
851 Chemung Street
Horseheads, New York 14825
Ph. 607.796.2216

PROJECT: Barrington West Lot 85
Town of Horseheads
Municipal Inspection
March 18, 2020

BY: Jessica Verrigni, CPESC, CPSWQ

