


Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control



Project Name	Biltmore Crossing	Date	5-23-14
Location	Biltmore Dr./Gardner Rd	Permit #	NYR 10X559
Weather Conditions	overcast	Entry Time:	8:51am
On Site Representative Present:	Lance - ZMK	Exit Time:	9:19

Construction Site Notes:

- Walked outside perimeter and there were no discharges and compost socks are in fact.
- Construction entrance looks good - min. tracking.
- Pond construction almost completed. Contracted said will be seeded and mulched by end of day.

Yes	No	N/A	
<input checked="" type="checkbox"/>			All erosion and sediment control measures installed/constructed
<input checked="" type="checkbox"/>			All erosion and sediment control measures maintained properly
	<input checked="" type="checkbox"/>		Are there currently more than 5 acres disturbed w/o prior approval
		<input checked="" type="checkbox"/>	Have stabilization measures been initiated in inactive areas <b>No Inactive Areas</b>
<input checked="" type="checkbox"/>			Are permanent stormwater control measures being implemented?
	<input checked="" type="checkbox"/>		Was there a discharge into the receiving water on the day of inspection?
	<input checked="" type="checkbox"/>		Evidence of turbidity or oil in the receiving waters
<input checked="" type="checkbox"/>			Are weekly inspections being performed?
<input checked="" type="checkbox"/>			Are the inspections being performed by a qualified individual?

Corrections Needed:

- Concrete washout is almost at capacity.

<input checked="" type="checkbox"/> Satisfactory	<input type="checkbox"/> Marginal	<input type="checkbox"/> Unsatisfactory
Date	Inspector	
5-23-14	Jessica Vernaghi	



851 Chemung Street  
Horseheads, New York 14845  
Ph. 607.796.2216

**PROJECT:** Biltmore Crossing  
Town of Horseheads  
Municipal Inspection  
May 23, 2014

**BY** Jessica Verrigni, CPESC, CPSWQ



Concrete washout area- This is almost at capacity.  
Will require maintenance soon.



Stormwater pond is almost complete.



Area that has not been disturbed yet.



Topsoil pile where material from pond and building pads is being stored.





CHEMUNG  
COUNTY  
STORMWATER  
COALITION

851 Chemung Street  
Horseheads, New York 14845  
Ph. 607.796.2216

<b>PROJECT:</b>	Biltmore Crossing
	Town of Horseheads
	Municipal Inspection
	May 23, 2014

<b>BY</b>	Jessica Verrigni, CPESC, CPSWQ
-----------	--------------------------------



Drainage along Biltmore Drive. Running clear.



Outlet of Stormwater Pond.



Existing drainage between project site and neighborhood to the North-West.



Biltmore Drive-No sediment is being tracked off site.