

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control



Project Name	Mickinkle SFH	Date	5-6-14
Location	Steege Hill	Permit #	NYR10X30Z
Weather Conditions	Partly Cloudy	Entry Time	10:44 a
On Site Representative Present	No one around	Exit Time	11:01 a

Construction Site Notes:

- + No active construction appears to be underway.
- + Need pond determination

Yes	No	N/A		
	X		All erosion and sediment control measures installed/constructed	Silt fence
	X		All erosion and sediment control measures maintained properly	Silt fence
			Are there currently more than 5 acres disturbed w/o prior approval	
	X		Have stabilization measures been initiated in inactive areas	
	X		Are permanent stormwater control measures being implemented	
	X		Was there a discharge into the receiving water on the day of inspection	
	X		Evidence of turbidity or oil in the receiving waters	
N/A			Are weekly inspections being performed?	
N/A			Are the inspections being performed by a qualified individual?	

Corrections Needed:

- Silt fence needs to be re-installed and maintained.
- Areas of open soil need to be stabilized immediately.
- Straw bales need to be removed from stream next to construction entrance

Satisfactory	Marginal	X	Unsatisfactory
Date	5-6-14	Inspector	Jessica Verrugni



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: McKinckle Property
Town of Big Flats
Municipal Inspection
May 6, 2014

BY Jessica Verrigni, CPESC, CPSWQ



Construction Entrance



Area of disturbance. No bare soil has been stabilized.



Pond is now filled.



No separation between construction and outlet of existing pond.



CHEMUNG
COUNTY
STORMWATER
COALITION

851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: McKinckle Property
Town of Big Flats
Municipal Inspection
May 6, 2014

BY Jessica Verrigni, CPESC, CPSWQ



Existing small pond



Hillside runoff.



Drainage from hillside has not been re-directed but put through a culvert pipe.



Pond dam