

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control



| | |
|---|-------------------------|
| Project Name: Jackson Farm Stormwater Detention Facility | Date: 6-4-15 |
| Location: Chambers Rd, Big Flats | Permit #: NYR10 |
| Weather Conditions: OVERCAST | Entry Time: 9:30 |
| On-Site Representative Present: TODD | Exit Time: 10:00 |

Construction Site Notes:

| |
|--|
| -hauling top soil out of storm water basin area. |
| |
| |
| |
| |
| |
| |
| |
| |
| |

| Yes | No | N/A | |
|-----|----|-----|---|
| X | | | All erosion and sediment control measures installed/constructed |
| | X | | All erosion and sediment control measures maintained properly |
| | X | | Are there currently more than 5 acres disturbed w/o prior approval |
| | | X | Have stabilization measures been initiated in inactive areas |
| | | X | Are permanent stormwater control measures being implemented |
| | X | | Was there a discharge into the receiving water on the day of inspection |
| | X | | Evidence of turbidity or oil in the receiving waters |
| X | | | Are weekly inspections being performed? |
| X | | | Are the inspections being performed by a qualified individual? |

Corrections Needed:

| |
|---|
| -silt fence has been knocked down in the storm water basin area |
| |
| |
| |
| |

Satisfactory Marginal Unsatisfactory

| | |
|-------------|----------------------|
| Date 6-4-15 | Inspector MARK WATTS |
|-------------|----------------------|



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Jackson Farm Stormwater Pond
Town of Big Flats
Municipal Inspection
June 4, 2015

BY Jessica Verrigni, CPESC, CPSWQ



Construction Entrance has been re-surfaced with millings.



Silt fence needs to be fixed.



Area where topsoil is currently located and being hauled off site.

