

Chemung County Stormwater  
Construction Inspection  
Erosion and Sediment Control



Project Name: Jackson Farm Stormwater Detention Pond	Date: 7-29-15
Location: Chambers Rd Big Flats	Permit #: NYR10Z268
Weather Conditions: Sunny	Entry Time: 3:49
On-Site Representative Present: none	Exit Time: 4:05

Construction Site Notes:

-no work is occurring at this time

Yes	No	N/A	
X			All erosion and sediment control measures installed/constructed
X			All erosion and sediment control measures maintained properly <i>state @ site fence needed</i>
	X		Are there currently more than 5 acres disturbed w/o prior approval
X			Have stabilization measures been initiated in inactive areas
		X	Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
X			Are weekly inspections being performed?
X			Are the inspections being performed by a qualified individual?

Corrections Needed:

-no issues at this time.

Satisfactory	X	Marginal	Unsatisfactory
Date	7/29/15	Inspector	Jessica Vernigni



851 Chemung Street  
Horseheads, New York 14845  
Ph. 607.796.2216

<b>PROJECT:</b>	Jackson Farm Stormwater Pond
	Town of Big Flats
	Qualified Inspection
	July 29, 2015

<b>BY</b>	Jessica Verrigni, CPESC, CPSWQ
-----------	--------------------------------



Construction entrance is clean and clear of debris.



80% vegetation achieved on topsoil stockpile.



Majority of the site is stabilized.

