

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control

Project Name		Hickory View Apartments		Date	9/23/2014
Location		Hickory Grove Road Town of Big Flats		Permit #	NYR10V597
Weather Conditions		Sunny - cold		Entry Time:	10:05
On-Site Representative Present:		Bryan Robinson- Elmira Structures		Exit Time:	11:09
Construction Site Notes:		Greg Krause -Elmira Structures			
		-site is under full construction. Buildings footers are being poured.			
		-wetland berm has been installed.			
		-vegetated open swales have been stabilized and compost socks installed.			
		-Wenzel foreman is Ryan Rhode.			
Yes	No	N/A			
X			All erosion and sediment control measures installed/constructed		
X			All erosion and sediment control measures maintained properly		
	X		Are there currently more than 5 acres disturbed w/o prior approval		
X			Have stabilization measures been initiated in inactive areas		
X			Are permanent stormwater control measures being implemented		
	X		Was there a discharge into the receiving water on the day of inspection		
	X		Evidence of turbidity or oil in the receiving waters		
X			Are weekly inspections being performed?		
X			Are the inspections being performed by a qualified individual?		
Corrections Needed:					
-silt fence is going to need to be monitored throughout construction because it is placed so close to the buildings that it will have maintenance issues.					
-wetland berm was installed but we need verification that it was constructed properly. This verification can be proven through photographs taken during construction.					
-outlet structure on pond 1B has been installed and looks correct.					
Satisfactory		Marginal		Unsatisfactory	
Date		Inspector			
9/23/14		Jesse Verrigni			