

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control

Project Name Williams Honda	Date 1-29-15
Location CA 64 Big Flats	Per mit # NYR10Y507
Weather Conditions overcast - cold	Entry Time: 11:35
On-Site Representative Present: None	Exit Time: 11:41

Construction Site Notes:

Entire site is covered in snow and frozen.
No work is occurring at this time.

Yes	No	N/A	
		<input checked="" type="checkbox"/>	All erosion and sediment control measures installed/constructed
		<input checked="" type="checkbox"/>	All erosion and sediment control measures maintained properly
	<input checked="" type="checkbox"/>		Are there currently more than 5 acres disturbed w/o prior approval
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		Have stabilization measures been initiated in inactive areas
<input checked="" type="checkbox"/>			Are permanent stormwater control measures being implemented
	<input checked="" type="checkbox"/>		Was there a discharge into the receiving water on the day of inspection
	<input checked="" type="checkbox"/>		Evidence of turbidity or oil in the receiving waters
<input checked="" type="checkbox"/>			Are weekly inspections being performed?
<input checked="" type="checkbox"/>			Are the inspections being performed by a qualified individual?

Corrections Needed:

-no issues were seen.

Satisfactory <input checked="" type="checkbox"/>	Marginal	Unsatisfactory
Date 1/29/15	Inspector Joseph Verugni	