

Chemung County Stormwater
Construction Inspection
Erosion and Sediment Control

Project Name Williams Honda	Date 11/10/14
Location CR 64 Big Flats	Permit # NYR10Y507
Weather Conditions Cool-overcast	Entry Time: 10:18am
On-Site Representative Present: Gene Beers	Exit Time: 10:48am

~~Sketch of Project site - include Disturbed Areas:~~

Signed SWPPP on-site? Yes
4 Hr. Contractor training? Yes

Yes	No	N/A	
	X		All erosion and sediment control measures installed/constructed
X			All erosion and sediment control measures maintained properly
Not sure			Are there currently more than 5 acres disturbed w/o prior approval
X			Have stabilization measures been initiated in inactive areas
X			Are permanent stormwater control measures being implemented
	X		Was there a discharge into the receiving water on the day of inspection
	X		Evidence of turbidity or oil in the receiving waters
	X		Are weekly inspections being performed?
		X	Are the inspections being performed by a qualified individual?

Engineer approved modifications
have to check

Comments:

- Construction entrances are not installed
- Silt fence is installed at property w/ overflow parking but not at dealership site.
- Inspections have to occur once a week

Satisfactory Marginal Unsatisfactory

Date 11/10/14 Inspector Jessica Verugne

Every WEEK

Don't stop on

engineer removed

engineer removed



851 Chemung Street
Horseheads, New York 14845
Ph. 607.796.2216

PROJECT: Williams Honda
CR 64 Town of Big Flats
Municipal Inspection
November 10, 2014

BY Jessica Verrigni, CPESC, CPSWQ



Construction entrance



Berm created between properties will be seeded and mulched.



Overflow parking area has been graded and stabilized.



Construction entrance onto Fisherville Rd.-
Equipment is blocking entrance so traffic is driving around it and off the construction entrance.